



NEW ORLEANS DISTRICT
US ARMY CORPS OF ENGINEERS

LOCK AND WATERWAY STATUS 60 DAY FORECAST

Updated: 04 February 2021
Note:
This schematic is not to scale.



- Open
- Opening Imminent
- Closure Imminent
- Closed
- Open/Closed intermittently
- Special instructions/Restrictions

GULF OF MEXICO

See notes on following page for details of structure and waterway status.

STRUCTURE	NAVIGATION BULLETIN#	WORK ITEM	EFFECTIVE DATE	COMMENTS
IHNC Lock	21-16	Re-installing Tainter Valve (ONE DAYTIME CLOSURE)	08 Feb 2021	Inner Harbor Navigation Canal (IHNC) Lock will be closed to navigation on Monday, 8 February 2021, between 7:00 a.m. and 5:30 p.m., due to construction activities on the new canal end dolphin.
Old River Lock	21-12	Re-installing Tainter Valve (INTERMITTENT CLOSURES)	03 Feb 2021	At Old River Lock, commencing on or about 3 February 2021 and continuing through approximately 28 February 2021, mariners will be subject to intermittent delays to navigation (up to 12 hours) due to necessary work required to re-install a tainter valve. The closures will occur during daylight hours between 7:00 a.m. and 6:00 p.m.
Port Allen Lock	21-07 Update from 20-02	Damaged Floating Guidewall (SPECIAL RESTRICTIONS)	26 Dec 2020	At Port Allen Lock, the damaged section of the floating Guidewall is marked with 4 white flashing lights at night. Until permanent repairs are made, the following restrictions will apply until further notice: WESTBOUND RESTRICTIONS * The restriction on tow length has been lifted. * All tows with more than one barge are required to use an assist vessel. * Single barge tows will be permitted to lock westbound without an assist vessel. EASTBOUND RESTRICTIONS * Tows greater than 650' long are required to use an assist vessel on the head of the tow once they exit the lock into the river in order to steer clear of the damaged area at the end of the guide wall.
Old River Lock	21-01 Update from 20-187	Lowering Carriage Repairs (SPECIAL RESTRICTIONS)	05 Oct 2020	Tows entering Old River Lock are urged to use extreme caution while approaching and entering the lock chamber. Until approximately 30 April 2021, the following restrictions/instructions are required for passage: 1. Tows are to enter the Lock at DEAD SLOW speed. 2. All tows are restricted to no longer than 1100' in length. 3. All tows will line up along the floating guide wall before proceeding. 4. Two line-handlers with life vests and bumpers will be required on both approach and exiting of the Lock. 5. Vessels must be moored by bow and stern lines to floating timberheads.
Algiers Lock	20-197 Update from 20-172	Open (SPECIAL RESTRICTIONS)	On-going	Algiers Lock is currently open to navigation with normal locking hours of operation. However, tows are restricted in both directions to a maximum width and length of 54 feet W by 700 feet L or 70 feet W by 600 feet L. Mariners are advised to continue to avoid the end of the long, river end, guide wall. It is unstable and a hazard to mariners.
Bayou Boeuf Lock	19-109	Chamber Guide Wall Replacement (INTERMITTENT CLOSURES)	11 Sep 2019	Bayou Boeuf Lock is closed to navigation from 7 a.m. until 7 p.m. (Daylight Hours), Mondays thru Thursdays until approximately 30 May 2021 to construct the new south side chamber guide wall.
East and West Calumet Floodgate		Heavy Siltation (CLOSED)	31 October 2018	Continuing until further notice, East and West Calumet Floodgate will remain closed to navigation due to heavy siltation in the channel making it unsafe for navigation.
Charenton Floodgate		N/A (CLOSED)	Closed until further notice.	This structure was closed in 2005.

NOTES:

1) Updates to table are shown in **Bold**.

2) Radio channel #14 should be used to contact lock operators, except Berwick Lock, which uses channel #12.

3) For the latest lock status including gage data, check the following Lock Update website:

<http://www.mvn.usace.army.mil/LockStatus/>